Name of Work : Providing drinking water facilities in Jalahalli Village Colony and surrounding areas in ward no.16 Jalahalli, BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** Rajarajeshwari Nagara Division, BBMP, Bangalore.
Contractor/Agency	:	**Technical Manager,** KRIDL, Bangalore.
Total Cost	:	Rs.39.47 Lakhs
Date of Inspection	:	23.03.2018
Status of Bill	:	1st & Final Bill
In the Presence of	:	(a) **Assitant Engineer (W. No. 16),** BBMP, Bangalore.
	:	(b) **Mr. Mohan.G,** Sr.Engineer M/s Civil Quality Consultants & Engineers, Bangalore.

PMC Compliance Report

Sl.No	Description of the Item		Comments / observations
1	Earthwork in Surface excavation in Hard soil for levelling and lowering the ground manualy.....		Work done up to the billed quantity and Quality is satisfactory
2	Earthwork excavation for foundation of buildings, water supply, sanitary lines and electrical conduits.....		Work done up to the billed quantity and Quality is satisfactory
3	Cutting of road surface for pipeline trenches and disposing.....	:	Work done up to the billed quantity and Quality is satisfactory
4	Cutting of road surface for pipeline trenches and disposing.....	:	Work done up to the billed quantity and Quality is satisfactory
5	Providing and fixing Chorinated poly vinyl chloride (CPVC).....	:	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

6	Providing and fixing gun metal wheel valve confirming to IS Specification.....	:	Work done up to the billed quantity and Quality is satisfactory
7	Providing and fixing Chorinated poly vinyl chloride	:	Work done up to the billed quantity and Quality is satisfactory
8	Providing and constructing burn brick masonry with approved quality modular bricks standard size of class designation 7.5 Newton per sqmm		Work done up to the billed quantity and Quality is satisfactory
9	Providing and fixing in position bib cock of approved quality 25mm nominal bore.....	:	Work done up to the billed quantity and Quality is satisfactory
10	refilling available earth around pipe lines, cables in layers not exceeding 20cms.....	:	Work done up to the billed quantity and Quality is satisfactory
11	Placing tipper at loading point, loading with front end loader.....		Work done up to the billed quantity and Quality is satisfactory

Authorised Signatory
For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಯಶವಂತಪುರ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Scanned by CamScanner